

# **TECHNICAL ADVISORY**

### **DIVISION OF MOTORIST SERVICES**

DATE: 05/30/2018 Technical Advisory (TA) Number RS/TL18-016

**SUBJECT: Pilot Rebuilt Vehicle Inspection Program Ends** 

### **Overview:**

In 2013, the Florida Legislature's enactment of section 319.141, Florida Statutes, authorized the Department of Highway Safety and Motor Vehicles (DHSMV) to manage the Pilot Rebuilt Vehicle Inspection Program (PRVIP) in Miami-Dade County, allowing private parties to conduct rebuilt motor vehicle inspections. Authorization for the PRVIP is set to expire July 1, 2018, therefore, DHSMV will resume conducting all rebuilt motor vehicle inspections in Miami-Dade County.

#### **Details:**

To accommodate this change and maintain consistent standards in serving our customers, the DHSMV regional office located at the Mall of Americas will close June 22, 2018, and relocate to a new facility. NOTE: The DHSMV driver license service center located at the Mall of the Americas will remain open.

The new DHSMV motor vehicle service center will open July 2, 2018 at the following location:

DHSMV Bureau of Dealer Services Motor Vehicle Field Operations - Regional Office 12601 NW 42<sup>nd</sup> Avenue, Opa-Locka, Florida 33054

Beginning July 2, 2018, up to ten (10) rebuilt vehicle inspection applications per customer will be accepted each day at the new regional office location. Rebuilt vehicle applications must be brought to the new office and dropped off for review. Customers will be notified by telephone and/or email to confirm scheduled appointments to bring their vehicles in for physical examination. A vehicle lane assignment will be made at the time of appointment to allow DHSMV compliance examiners to inspect up to ten (10) rebuilt vehicles per customer daily. The compliance examiner will provide completed documents in sealed envelopes for each "passed"

rebuilt vehicle, which will allow a rebuilt title to be applied for at a local Miami-Dade Tax Collector or License Plate/Tag Agency.

# **Conclusion:**

If you need additional information, please contact your next level of management.